Work Order ID 7 4 October 6, 2011 1:41:45 PM			*748	02 *						Page 1
Item ID: D3560-042 Revision ID:		A	Accept	*N900	040	100*	s s	etup Star Stor	I VI	S1* S2*
Item Name: Arm Weldme				1					I Vi	. 7/
Start Date:	Start Qty: 4.00	*4*		Cust Item II	D:	•				
Required Date: 10/17/11	Req'd Qty: 4.00	*4*		Customer:	•		-			
Reference:							D	un Star	t dan s	— 4 4
Approvals: Process Pl	lan: M.L.J	Date: 11 10006	Tooling:	Da	ite:	:		-	1/1	R1*
QC:	V	Date:	SPC (Y/N):	Da	ite:			Stop	*N	R2*
Sequence ID/ Work Center ID	Operation Description		Set Up/ Run Hours	Tool ID			ccept ty	Reject Qty	Reject Number	Insp. Stamp
Praw Nbr جنيـ Re	vision Nbr	*		•	.:			.;As.	44.	
D3560 Re	v D									
*100 * *100* Bandsaw Jeaspa Bandsaw	BAND SAW Memo Cut blanks		0.00 F.K	. 11/11/0	9	·	4	ø		
icaspa Banusaw	Cut ofulling	o.750 long					-			
110	HAAS CNC VERTICAI	MACHINING #1	0.00							
110 HAAS I	Mama		0.00				<u> </u>			
HAAS CNC vertical machine #1		er Folio FA694 Rev: AA 2896" hole on manual mill as p r dwg D3560	& Dwg D3560 Rev: <u>\</u> er dwg D3560	- JL 11-11-	12	(l	1)			
120	QC2- Inspect parts off m	achine FAI/FAIB	0.00							
120 ^{QC}	Memo		0.00	11-11-12						

Quality Control

Dart Ae	rospace	e Ltd				•	, ,	
W/O:			W	ORK ORDER CHANGE	ES			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approva QC Inspecto
-		3						
		v • .		, to				
Dort No.		# 157%.			NOD: Vac I	Ja BOA	Data]
Part No		PAR #:						
	R	esolution:	Dispositio	n:	QA: N/C Clo	sed:	Date: _	
NCR:		1	WORK ORD	ER NON-CONFORMA	NCE (NCR)			
		Description of NC		Corrective Action Section		Verification	Approval	Approva
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspecto
		<i>-</i> -						
							·	***
					•			
		·						

74802

Page 2

October 6, 2011 1:41:45 PM *N900040100* Item ID: D3560-042 Accept Setup Start **Revision ID:** Stop Arm Weldment Item Name: Start Date: 10/06/11 Start Qty: 4.00 **Cust Item ID:** Required Date: 10/17/11 Req'd Qty: 4.00 **Customer:** Reference: Run Date: Date: Approvals: **Process Plan: Tooling:** Stop Date: **SPC (Y/N):** . Date: Sequence ID/ **Operation Tool ID** Tool # Plan Reject Reject Set Up/ Accept Insp. Code Work Center ID Description **Run Hours** Qty Qty Number Stamp QC8- Inspect parts - second check** 0.00 .130 out ululia *120* 0.00 Memo **Quality Control** 140 0.00 Large Fab *140* Large Fab 0.00 Memo Large Fab 1-Weld assembly as per dwg D3560 1- clean material (buff bracket and bottom of arm with blue pad) 2- set up bracket and arm on jig 3- preheat bracket and arm with torch 4- clean before welding with brush 5- set up machine to 135 amps 6- weld across bottom and top ends 7- reheat with torch (65 deg C) 8- on one side weld from bottom to top half way 9- same for other side (half way) 10- from half way point weld the rest of the first side (ease off pedal near 11- same for remaining side (ease off pedal near end)

Dart	Aeros	pace	Ltd
------	--------------	------	-----

	=							
W/O:			W	ORK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
							ł	
			· · · · · · · · · · · · · · · · · · ·					
Part No	:	PAR #:	Fault Cate	egory:	_ NCR: Yes	No DQA :	Date: _	·
	Re	esolution:	Disposition	on:	_ QA: N/C Cl	osed:	Date: _	
NCR:			WORK ORE	DER NON-CONFORM	ANCE (NCR	2)		
DATE	STED	Description of NC			ion B	Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
						•		
							·	
							,	

Work Ord October 6, 2011				*74	R02*							Page 3
Item ID: Revision ID: Item Name:	D3560-042 Arm Weldme	ent		Accept	*N900	040	100)*	Setup	Start Stop	*N: *N:	S1* S2*
Start Date: Required Date: Reference:	10/06/11	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item I Customer:	D:						
Approvals:		an:		Tooling: SPC (Y/N):		ate:			Run	Start Stop	*NI *NI	R1* R2*
Sequence ID/ Work Center II 150 *150* QC Quality Control	D	Operation Description QC5- Inspect part compl	leteness to step on W/O	Set Up/ Run Hours 0.00	Tool ID	Tool #	Plan Code	Accep Qty (x9)	Qty		Reject Number	Insp. Stamp
*160 *160* QC Quality Control		QC9- Inspect visual per o	QSI004- Fusion Welds	0.00				4	e D		BSI	1 <u>-1117</u>
170 *170* HandFinish		Chemical Conversion Co	oat per QSI005 4.1	0.00			4	/X	J	MI	fli	447

Hand Finishing

	•							
W/O:			WO	RK ORDER CHANG	ES			
DATE	STEP	PRO	OCEDURE CHAN	NGE	Ву	Date Qty	Approval Chief Eng /	Approval QC Inspector
				,			Prod Mgr	
			· .			<u> </u>		
Part No	:	PAR #:	Fault Categ	jory:	NCR: Yes	No DQA:	Date: _	· · · · · · · · · · · · · · · · · · ·
	Re	solution:	Disposition	ı:	_ QA: N/C Cld	osed:	Date: _	
NCR:			WORK ORDE	R NON-CONFORMA	NCE (NCR)		
		Description of NC		Corrective Action Section		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
							·	
		•						

Work Orde October 6, 2011					*748	302*					Pa	ge 4
Revision ID:	D3560-042 Arm Weldmer	nt			Accept	*N900	1 040	1003	s Setu	p Start Stop	*NS1 [*]	k *
Start Date: Required Date: Reference:	10/06/11	Start Qty: 4.00 Req'd Qty: 4.00		*4* *4*		Cust Item Customer					יאוו	
Approvals:	Process Pla	n:	Date:		Tooling: SPC (Y/N):		Date:		Run	Start Stop	*NR1	*
Sequence ID/ Work Center II 180 *180* QC Quality Control)	Operation Description QC3- Inspect Part Finish Memo			Set Up/ Run Hours 0.00	Tool ID	Tool #		-		Reject Insp. Number Stamp	, , _(\vec{\vec{\vec{v}}}
190 *1Q∩* Small Fab Small Fab		Small Fab Memo 1-Press bush	ing in D3560	arm per dwg	0.00 0.00 D3562				JS1.	<u> </u>	18 D	
200 *200* QC Quality Control		QC5- Inspect part comple	teness to step	o on W/O	0.00	Nul18			cy		<u>,</u>	Name and American

W/O:			V	ORK ORDER CHANG	ES			
DATE	STEP	PRO	CEDURE CH	ANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
-							Floativigi	
								
Part No	•	PAR #:	Fault Cat	tegory:	NCR: Yes	No DQA:	Date: _	
	R	esolution:	Dispositi	ion:	_ QA: N/C Clo	sed:	Date: _	
NCR:		\	WORK ORI	DER NON-CONFORMA	NCE (NCR))		
		Description of NC		Corrective Action Section		Verification	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
						,		
	,							
	1		t I			i		ŀ

Work Ord				*748	302*						Page 5
Item ID: Revision ID: Item Name:	D3560-042			Accept	*N900	040	1100)*	Setup Sta	1 /	IS1* IS2*
Start Date: Required Date: Reference:	10/06/11 10/17/11	Start Qty: 4.00 Req'd Qty: 4.00	*4* *4*		Cust Item 1 Customer:	ID:					
Approvals:	Process Pl	lan:	Date:	Tooling:	D	ate:]	Run Sta	17	R1*
	QC:		Date:	SPC (Y/N):	D	ate:			Sto	^{)p} *N	R2*
Sequence ID/ Work Center II)	Operation Description Identify as per dwg & St	ock Location: WA	Set Up/ Run Hours	Tool ID	Tool#	Plan Code	Accept Qty	Reject Qty	Reject Number	Insp. Stamp
210 Packaging Packaging		Memo	IN STEP CELL***	0.00	K11-11	1.22		4	- D		
220		QC21- Final Inspection -	- Work Order Release	0.00						· .	1
±000±		QC21- Final hispection -	WOIR Older Neicase	0.00					1 1	1/-	, X

0.00

Memo

Quality Control

M/11/21 A)

W/O:			WC	ORK ORDER CHANG	ES					
DATE	STEP	PR	OCEDURE CHA			Зу	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
						-			Prod Mgr	
-										
Part No	•	PAR #:	Fault Cate	gory:	NCR:	Yes N	lo DQA	\:	_ Date: _	
	Re	esolution:	Disposition	n:	_ QA: N	/C Clos	sed:		Date: _	
NCR:			WORK ORD	ER NON-CONFORMA	NCE (NCR)				
	0750	Description of NC		Corrective Action Section			Verific	ation	Approval	Approval
DATE	STEP	Section A	Initial Chief Eng	Action Description Chief Eng		Sign & Date	Section		Chief Eng	QC Inspector
		•						İ		
									·	
						,				
								:		
					· •	~			,	
							New year			
						`~				

Picklist Print Page 1 October 6, 2011 1:41:50 PM *74802* Work Order ID: 74802 D3560-042 *D3560-042* Parent Item: Parent Item Name: Arm Weldment Start Date: 10/06/11 Required Date: 10/17/11 Start Oty: 4.00 Required Oty: 4.00 IPP Rev:A New Issue 07.05.24 EC Comments: verified by: DD IPP rev B ECN 987 07.10.09 EC DD verified by: EC IPP Rev:C ECN1048 07-12-18 Replacement Mfg/ Unit of Qty on Oty per Kit Component Item ID/ Bin Primary Last Route Total Qty Date Status Hand Seq ID Measure Item Name Item ID Item Location Location Issued Issued Purch **Qty** D2808 No 100 Each 18.0000 Manufactured ** *D2808* Bushing Loc Qty Loc Code Location GA 18 32896 2 16 71879 140 14.4750 1.395 5.873684 M6061T6B0.500X05.00 Purchased No *M6061T6B0 500X05 000* ** 6061-T6 Bar .500 x 5.00 Location Loc Oty Loc Code MAT004 14.475 FK 11/11/09 6.935 112154 117933 7.54 119346 190 17.0000 D3592-1 Manufactured No Each **

Plate

Loc Qty Loc Code Location WA002 17 2 47015 15 48517

W/O:			V	ORK ORDER CHANGI	ES			
DATE	STEP	PRO	OCEDURE CH	IANGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
•								
Part No	.	PAR #:	Fault Ca	tegory:	NCR: Yes	No DQA:	Date: _	
	R	esolution:	Disposit	ion:	QA: N/C CI	osed:	Date: _	
NCR:			WORK OR	DER NON-CONFORMA	NCE (NCF	R)		
DATE	STEP	Description of NC		Corrective Action Section		Verification	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign 8 Date	Section C	Chief Eng	QC Inspector
		·						
		·						

DART AEROSPACE LTD	Work Order:	14802
Description: Arm	Part Number:	D3560-2
Inspection Dwg: D3560 Rev: D		Page 1 of 1


FIRST ARTICLE INSPECTION CHECKLIST

X	First Article		Prototype
---	---------------	--	-----------


Drawing Dimension	Tolerance	Actual Dimension	Accept	Reject	Method of Inspection	Comments
Ø0.507	+0.000/-0.001	.5065	//		mic 12-4	
Ø0.196	+0.005/-0.001	-197			Van JL3	
Ø1.000	+0.010/-0.001	1003			1	
0.500	+/-0.010	.495				· ·)
0.250	+/-0.010	-251				!
0.275	+/-0.010	276	/			
0.188	+/-0.010	189				. (
2.000	+/-0.010	2001				
1.700	+/-0.010	1-701	/			
Ø0.385 x 100°	+/-0.010 x 0.5°	350X1W				
0.250 Deep	+/-0.010	,251				<u>.</u>
e.						. 3
				-		
						`

Measured by:	Audited by:		Prototype Approval:	N/A
Date: 11-11-12	Date:	11/1/12	Date:	N/A


Rev	Date	Change	Revised by	Approved
Α	07.01.17	New Issue P/O D3560-042	KJ/JLM	
В	07.06.13	Dimensions updated per Dwg Rev B	KJ/JLM,	. 4
С	09.06.11	Dwg Rev updated	KJ 947	8/



W/O:	· [WC	RK ORDER CHAN	GES				
DATE	STEP	PR	OCEDURE CHAI	NGE	Ву	D	ate Q	Approval Chief Eng / Prod Mgr	Approval QC Inspector
			·						
Part No	:	PAR #:	Fault Categ	jory:	NCR: Y	es No	DQA: _	Date: _	
Resolution:			Disposition: (QA: N/C Closed:			
NCR:			WORK ORDE	R NON-CONFORM	IANCE (N	CR)			. •
DATE	STEP	Description of NC Section A	Initial	Action Description	ction B	jn&∥	Verification Section C		Approval QC Inspector
			Chief Eng	Chief Eng	D	ate			
						_			
								·	
								·	
	1 1				· ·	.		}	




W/O:			WC	ORK ORDER CHANG	SES			
DATE	STEP	PRO	OCEDURE CHA	NGE	Ву	Date Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				A MIL.				
								<u></u>
Part No	:	PAR #:	Fault Cate	gory:	_ NCR: Yes	No DQA:	Date: _	-·
	Re	esolution:	Dispositio	n:	QA: N/C Clo	sed:	Date: _	
NCR:		,	WORK ORD	ER NON-CONFORM	ANCE (NCR)		
DATE	STEP	Description of NC			tion B	Verification	Approval	Approval
DATE	SIEP	Section A	Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Chief Eng	QC Inspector
		•						
								
					`~			



Dart Aerosp	ace Ltd
-------------	---------


W/O:			W	ORK ORDER CHANG	BES				
DATE	STEP	PRO	PROCEDURE CHANGE			Date	e Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
				· · · · · · · · · · · · · · · · · · ·					
Part No	•	PAR #:	Fault Cate	gory:	_ NCR: Ye	s No	DQA:	_ Date: _	
Resolution:			Dispositio	Disposition: QA: N/C Closed: D					
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NO	R)			
DATE	STEP	Description of NC			tion B		rification	Approval	Approval
	J.E.	Section A	Initial Chief Eng	Action Description Chief Eng	Sigr Dat		Section C	Chief Eng	QC Inspector
								·	
	 - - -					-			
					``_	İ		ĺ	



O

Dart Aerospace Ltd	
--------------------	--

W/O:			W	ORK ORDER CHANG	SES		· · · · · · · · · · · · · · · · · · ·			
DATE	STEP	PRO	PROCEDURE CHANGE			Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector
										200
Part No	•	PAR #:	Fault Cate	egory:	_ NCR:	Yes N	o DQ A		Date:	
Resolution:			Disposition	Disposition: QA: N/C Closed: D						
NCR:			WORK ORD	ER NON-CONFORM	ANCE (NCR)				
DATE	STEP Description of NC		Corrective Action Section B			ign &	Verification		Approval	Approval
		Section A	Initial Chief Eng	Action Description Chief Eng		Date Date	Sectio	n C	Chief Eng	QC Inspector
		·								
						*				



Dart	Aeros	pace	Ltd
------	--------------	------	-----

W/O:	·			WORK ORDER CHANGES							
DATE	STEP		PRO	OCEDURE CHANGE		Ву	Date	Qty	Approval Chief Eng / Prod Mgr	Approval QC Inspector	
		,			3				-		
			**· .								
					\						
Part No):	`	PAR #:	Fault Category:		ICR: Yes	Nò DQ	A:	Date: _		
	R	esolution:	· · · · · · · · · · · · · · · · · · ·	Disposition:		A: N/C C	losed:		Date: _	<u> </u>	
NOD.			1	WORK ORDER NON-CONFORMANCE (NCR)							

NCR:		WORK ORDER NON-CONFORMANCE (NCR)						
DATE	STEP	Description of NC Section A	Corrective Action Section B			Verification	Approval	Approval
			Initial Chief Eng	Action Description Chief Eng	Sign & Date	Section C	Approval Chief Eng	Approval QC Inspector
							1/2n 	
,						,		
			,					
							,	
				r r				